




WFV-Series Software Upgrading


1. Click the cross icon and then click  to close CNC App.




2. Please copy the latest upgrading file folder after finishing un-zip it.



3. Click and open the file folder. Then find the update icon and double click it.



4. There will pop up a box then wait for it finish.



```
CAWindows\system32\cmd.exe
C:\Users\SOL\Desktop\update_package_20200827181926_v0.71\default\GSM_720S13.ini
C:\Users\SOL\Desktop\update_package_20200827181926_v0.71\default\EN_03_5008M.in
i
C:\Users\SOL\Desktop\update_package_20200827181926_v0.71\default\EN_04_5008M.i
ni
C:\Users\SOL\Desktop\update_package_20200827181926_v0.71\default\EN_05_5008M_0
BS.ini
C:\Users\SOL\Desktop\update_package_20200827181926_v0.71\default\EN_06_502M.in
i
C:\Users\SOL\Desktop\update_package_20200827181926_v0.71\default\EN_07_525MW.in
i
C:\Users\SOL\Desktop\update_package_20200827181926_v0.71\default\EN_08_525MW_AB
S.ini
C:\Users\SOL\Desktop\update_package_20200827181926_v0.71\default\ODM_FP-$1008.i
ni
C:\Users\SOL\Desktop\update_package_20200827181926_v0.71\default\ODM_FU210.in
i
C:\Users\SOL\Desktop\update_package_20200827181926_v0.71\default\ODM_P_FU210.in
i
11 File(s) copied
C:\Users\SOL\Desktop\update_package_20200827181926_v0.71\help\default\000_CHT\h
elp.pdf
C:\Users\SOL\Desktop\update_package_20200827181926_v0.71\help\default\001_CHS\h
elp.pdf
```

5. Click the CNC icon to launch CNC App and continue production.

